# 1PCRT CONNECT

DOCK



72307 - CONNECT DOCK

### IPCRT CONNECT

#### DOCK

### **IPORT CONNECT DOCK Install Manual**

Thank you for purchasing the all new IPORT CONNECT Platform. We hope you enjoy this revolutionary new system and if at any time you need more assistance please contact IPORT Tech Support via Online chart or through our help desk.

- IPORT Team

### Whats in box:

- 1 IPORT CONNECT DOCK
- 1 IPORT POWER SUPPLY
- 1 Info Card

#### **POWER SPECS**

INPUT: 110-240V | AC 50/60 Hz

CRADLE OUTPUT 1: 5V 3A, PD 9V 3A

CRADLE OUTPUT 2: 5V 1.5A

(Output 2 is for electronic accessories and requires a CONNECT PRO Case with accessories installed)














FCC PART 15B CLASS B AS/NZS 60950 AS/NZS CISPR22 EN 55032:2015+A11:2020 BS EN 55035:2017+A11:2020

## 1PCRT CONNECT

### DOCK

1. Remove DOCK and Power Supply from the box and place on a table.


2. Insert the barrel connecto into the bottom side of the dock.




## IPCRT CONNECT

### DOCK

3. Rotate the wire retention clip towards the front of the dock. Run the wire around the retention post and rotate the clip back into place.





## LPCRT CONNECT

#### DOCK

4. Place the CONNECT Dock in the desired location. Plug in the power adapter into AC power and place IPORT CONNECT Case onto a Dock to initiate charging.

